

Tech Bulletin

Hand Crank to Explosion Proof Motor Requirements

Hand Crank to Explosion Proof Motor - Kit #S600781 CA33112 L to EA33112 L10AX

| Qty. | Part # | Description |
|------|---------|-----------------------|
| 1 | 260430 | Drive Motor |
| 1 | 260456 | Spacer |
| 1 | 260406 | Drive Chain |
| 1 | 260407 | Spool Gear |
| 1 | 260434 | Motor Gear |
| 4 | 300039 | Washer |
| 4 | S2-52 | Hex Cap Screw |
| 4 | S44-3 | Machine Screw |
| 6 | S27-112 | Flat Cap Socket Screw |
| 6 | S79-3 | Flange Nut |
| 6 | 260410 | Gear Spacer |

Hand Crank to Explosion Proof Motor - Kit #S600782 CA33112 L to EA33112 L12DX

| Qty. | Part # | Description |
|------|---------|-----------------------|
| 1 | 260583 | Drive Motor |
| 1 | 260456 | Spacer |
| 1 | 260406 | Drive Chain |
| 1 | 260407 | Spool Gear |
| 1 | 260434 | Motor Gear |
| 4 | 300039 | Washer |
| 4 | S2-52 | Hex Cap Screw |
| 4 | S44-3 | Machine Screw |
| 6 | S27-112 | Flat Cap Socket Screw |
| 6 | S79-3 | Flange Nut |
| 6 | 260410 | Gear Spacer |

Form # TB0013 Rev: 5/2012

Hand Crank to Explosion Proof Motor - Kit #S600783

CA33112 L to EA33112 L24DX

| Qty. | Part # | Description |
|-------------|---------------|-----------------------|
| 1 | 260626 | Drive Motor |
| 1 | 260456 | Spacer |
| 1 | 260406 | Drive Chain |
| 1 | 260407 | Spool Gear |
| 1 | 260434 | Motor Gear |
| 4 | 300039 | Washer |
| 4 | S2-52 | Hex Cap Screw |
| 4 | S44-3 | Machine Screw |
| 6 | S27-112 | Flat Cap Socket Screw |
| 6 | S79-3 | Flange Nut |
| 6 | 260410 | Gear Spacer |