

# Tech Bulletin

## Series 80000 New Latch Mounting Bracket Assembly

---


### Low and Medium Pressure Models

<b>Low Pressure</b>	<b>Medium Pressure</b>
81000 OLP	82000 OMP
81000 OLP	82000 OMP
81100 OLP	82075 OMP
82000 OLP	83000 OMP
82075 OLP	83050 OMP
82100 OLP	82000 OMS
83000 OLP	83000 OMS
83050 OLP	82000 OMS-S
F83000 OLP	83000 OMS-S
F83050 OLP	
GC83050 OLP	
LP82000 OLP	
LP83000 OLP	
PAV83050 OLP	
PAV83075 OLP	
81000 OLS	
82000 OLS	
83000 OLS	
81000 OLS-S	
82000 OLS-S	
83000 OLS-S	
LP82000 OLS	
LP83000 OLS	


Form #TB0024 Rev: 4/2012

For any reel built before May of 2012, the entire Latch Pawl and Mounting Bracket Assembly will need to be ordered as a replacement for these reels, which will include the newly designed Latch Mounting Bracket, the newly designed Latch Spring, the Latch Pawl Assembly and the associated hardware needed for this new assembly. Parts of the Latch Pawl and Mounting Bracket Assembly for these reels are not to be sold individually for replacement.

THE BELOW PICTURE SHOWS THE OLD DESIGN FOR THE LATCH MOUNTING BRACKET ASSEMBLY (PRIOR TO MAY 2012)



THE BELOW PICTURE SHOWS THE NEW DESIGN FOR THE LATCH MOUNTING BRACKET ASSEMBLY; 600643-XX SHOWN IN RED (AFTER MAY 2012)



Assembly part number 600643-XX, where XX represents the paint color code, will need to be ordered for the following reel models:

<b>Low Pressure</b>	<b>Low Pressure</b>	<b>Medium Pressure</b>
81000 OLP	F83000 OLP	82000 OMP
81100 OLP	F83050 OLP	82075 OMP
82000 OLP	GC83050 OLP	83000 OMP
82075 OLP	LP82000 OLP	83050 OMP
82100 OLP	LP83000 OLP	
83000 OLP	PAV83050 OLP	
83050 OLP	PAV83075 OLP	

Assembly part number 600729 will need to be ordered for the following reel models:

<b>Low Pressure</b>	<b>Low Pressure</b>	<b>Medium Pressure</b>
81000 OLS-S	LP82000 OLS	82000 OMS-S
82000 OLS-S	LP83000 OLS	83000 OMS-S
83000 OLS-S		

Assembly part number 600729-1 will need to be ordered for the following reel models:

<b>Low Pressure</b>	<b>Medium Pressure</b>
81000 OLS	82000 OMS
82000 OLS	83000 OMS
83000 OLS	

THE BELOW PICTURE SHOWS THE NEW DESIGN FOR THE LATCH MOUNTING BRACKET ASSEMBLY

